# Porsche 2.9 324KW/440 PS



The product described in the guidance was developed, manufactured and controlled considering the necessary safety reguirements.

The product must be installed properly to ensure a proper function and avoid danger for persons and things.

Please read this installationguide inclusive safety instructions carefully.

## Scope of supply

Quantity	Article
1x	Tuningbox
1x	Loom
1x	Bridgeplug
1x	Fastening kit



- 1. Open the hood.
- 2.Turn the ignition off!
- 3. Remove the ignitionkey!
- 4. Close and lock all doors!
- 5.Do not open any doors while installing the tuningkit!
- 6. Wait 5 minutes before beginning the installation









In order to avoid damages at electronic vehicle components, you have to be sure that you have done all necessary methods for **electostatic discharge** .


Install the electronic in an waterproof, heat and vibrationless place. Do not make any changes at the tuning-kit!

Do not expand or shorten the loom.

Date: 10.08.2018 Page: 1 Version 2

# Porsche 2.9 **324KW/440** PS





### **Overview:**

The tuningkit has to be attached to the following points:

- Boost pressure sensor 1 + 2
- Manifold sensor 1+ 2
- Camshaft sensor
- Power supply

### **Required tools:**

Ratsche mit Verlängerung (13er, 17er)


### **Preperation:**

- Move the individual strands of the loom to the associated plug connectors
- Put the required tools by your side ( if needed )
- Take the fastening material at your side
- To get the maximum power enhancement, you have to use "super plus" (98 ROZ)

Date: 10.08.2018 Page: 2 Version 2

# Porsche 2.9 324KW/440 PS





### 1. Preparation


Before you can start the installation, you must remove the engine cover. To do this, loosen the screws on the left and right of the strut bar. Then the strut bar can be folded away to the right or left.

The engine cover is only attached with clips



# Porsche 2.9 324KW/440 PS






### 2. Manifold 1

Disconnect the plug from the manifold sensor 1.


Attach the manifold plug to the new loom.

Connect the plug of the new loom the manifold sensor 1.



# Porsche 2.9 324KW/440 PS






### 3. Manifold 2

Disconnect the plug from the manifold sensor 2.


Attach the manifold plug to the new loom.

Connect the plug of the new loom the manifold sensor 2.



# Porsche 2.9 324KW/440 PS






## 4. Boost pressure sensor 1

Disconnect the plug from the boost pressure sensor 1.

Attach the boost pressure plug to the new loom


Connect the plug of the new loom the boost pressure sensor 1.





# Porsche 2.9 324KW/440 PS





### 5. BOOST PRESSURE SENSOR 2

Disconnect the plug from the boost pressure sensor 2.


Attach the boost pressure plug to the new loom

Connect the plug of the new loom the boost pressure sensor 2.



# Porsche 2.9 324KW/440 PS






### 5. Camshaft sensor

Disconnect the plug from the camshaft sensor

Attach the camshaft sensor plug to the new loom

Connect the plug of the new loom to the camshaft sensor






- ♦ The plug must be as show on the picture will be with the shallow edge on the side of the ridge.
- With some higher force, it is possible to push the plug with the round side on the ridge!!!



Date: 10.08.2018 Page: 8 Version 2


# Porsche 2.9 324KW/440 PS





### 5. Power supply

To access the bridging pole, please loosen the cover.



Connect the red cable of the new wiring harness to the positive pole of the battery.

Connect the black cable of the new harness to the negative (ground) of the car.

# Porsche 2.9 324KW/440 PS





### 6. tuningbox

Finally install the cable towards a suitable position

The plugs must be engage, so that a safe connection is ensured

Fix the cable with cable ties

Connect the tuningbox to the new loom



### 7. jumper plug

By using the jumper the vehicle is put in the original condition.

As soon as you connect the cable loom with the jumper plug the car is in original condition.

## Porsche 2.9 324KW/440 PS



## **FAQ**

Error Description:	How to fix this error:	
	Please check the plug-in connection of the affected sensors all sensors are plugged in properly.	, make sure that
Engine doesn't start	Make sure that the 12V power supply is connected correctly	y, if available.
	Unplug the chiptuning box, plug the bridge connector, and twhether the error persists.	then check
Engine "jerky"	Check all connections, have you plugged in a plug incorrectl properly locked?	y or is it not
	Have you removed one of the plugs under current? (Open t the doors, close and wait for 5 minutes)	he hood, close
Car goes immediately into limp mode	Please check the wiring harness.	
	Unplug the box, insert the bridge connector, and then check error persists.	k whether the
	Make sure you are on the correct plugs.	
Car without power increase	Please check the goods for possible damages and compare on the box with the one in the webshop.	the item number
	Only gasoline: Make sure you have fueled the right fuel with (98 RoZ) or a higher quality.	n min Super Plus
Strong soot development in the	Only after consultation, change the chip tuning box down by ing switch by 1 to 2 steps.	y the rotary cod-
engine	If you have a chiptuning box with app, set it to "ECO".	
	Please unplug the chiptuning box and plug the bridge plug.	
Engine has misfire	Then try again to see if the error still occurs.	
	Then try again to see if the error still occurs.	
Date: 10.08.2018	Page: 11	Version 2